



### Z car Bio











#### COVID-19

- SARS-CoV-2 is the coronavirus that causes COVID-19
- Air borne coronavirus pathogens 'live' up to 3hrs.
- Hard-surfaces;
  - Cardboard <24hrs</p>
  - Copper <4hrs</p>
  - S.S. and Plastic <72hrs</li>
- Hard-surface disinfectants\* e.g. 'Lysol Multi-Surface Cleaner' Active ingredients:
- Benzalkonium Chloride
  - Hydrochloric Acid
  - Citric Acid
  - Benzyl Ammonium
  - Alcohol Anhydrous
  - Sodium Hypochlorite

Note: hand sanitizers with less than 70% alcohol content will NOT kill coronavirus



## **Surface Artistry**

#### **Paint types**

- Lacquer; Vintage and Antiques
- Enamels; Classics
- Acrylic-Enamels; Modern

#### **Process**

Single Stage

Base-Clear


#### **Manufacturing Differences**

- Domestic and European; thicker and more durable
- Pac-Rim; thinner and easier to chip





### **Surface Preparation**



#### **'PAINT CORRECTION'**



### Shiny & New

#### Decontaminate

Pre-soak low and high pH

•Wash

2 bucket system pH Neutral

- Clay Bar
- Cutting (Buffing)
- Polishing

Pre-coating prep

Coatings

Waxes

**Polymers** 

**Ceramic Coatings** 





### restoshop.com

Paint Correction Ceramic Coatings Paint Protection Film



Classic Car Restoration Specializing in Datsun / Nissan









# Thank you OZC!



519 901 2638

jackmac@restoshop.com

